ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	2	Chowdeshwari Ward
Street ID	**Street Name**	**Significant Landmark**
W0280, W0391	2nd Crs, Lakshmi Sagar Lyt, NA	13th D Cross Roads of Eastern Side kondappa Layout
Segment No.	**Total Length (m)**	
2/S-W0280/S010614	109.57	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	28.91	77.592131	13.109483	77.592391	13.109541	W0387	W0391
2	80.66	77.592619	13.109601	77.593254	13.109859	W0391	YELAHANKA LAKE

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Drains at 13th D Cross Roads of Eastern Side kondappa Layout in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	800000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Others	DRAIN
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Drains at 13th D Cross Roads of Eastern Side kondappa Layout in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	002-15-000015
Work Order No.	**Work Order Date**	**Period of Extention**
EE (YNK.D) E-PMT-04/WO/68/2014-15	28/01/2015	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/04/2015	29/04/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
LINGRAJU		0.00
Phone No.	**E-Mail ID**	
9945799229		

E-mail : visnwanath.ia@civiltechconsultants.com / info@civiltecnconsultants.com

d Inspection Details

umber of Trees	Any Other Information	Name
3		RAMASANJEEVAIAH
Date of Inspection	**Remarks**	
29/01/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

...@civiltechconsultants.com

Drain Condition

This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	29/01/2017	28/02/2017	COMPLETED
SE	VASU K M	29/01/2017	28/02/2017	COMPLETED
EE	SRINIVAS	29/01/2017	28/02/2017	COMPLETED
AEE	G.B. PRABHAKAR	29/01/2017	28/02/2017	COMPLETED
AE	RAMASANJEEVAIAH	29/01/2017	28/02/2017	COMPLETED
AE	RAMASANJEEVAIAH	29/01/2017	28/02/2017	COMPLETED

info@civiltecnconsultants.com / info@civiltecnconsultants.com